

## **Oakland University, Rochester, MI**

Bridge collapsed in the Summer and the University needed a solution before the Fall Semester started





BEFORE

**30 DAYS LATER** 

Art Thureson, Inc was notified by Oakland University that a concrete bridge deck collapsed to a dormitory and a second bridge did not pass inspection. They needed a solution. With fall registration booked and the University needing two dormitories open and ready for the Fall semester, Art Thureson, Inc designed & supplied two 50' bridges in about 30 days. Bridges were set in one day, concrete poured and approach work completed in time for Fall courses.

For additional photos, visit:

## www.artthuresoninc.com



Abutment solution at each building



Installed on time!